


FIG. 1



865090 " 426060

FIG. 2





FIG.3






FIG. 4(a)




FIG. 4(c)




FIG. 4(b)




FIG. 4(d)

090092374-090558




FIG. 5(a)




FIG. 5(b)





FIG. 5(c)

卷之三


FIG. 6



8650980 74 326060

865090 " 44-26060

FIG. 7



865090 - 112E26060

FIG. 8






FIG. 9



865090-4726060

FIG. 10



BLOOD TO OXYGENATOR
PUMP VIA FEMORAL
RETURN CATHETER